

Current Open Issues

Issue ID	Title	Location	Type	Priority	Assigned To	Created
71	Painting a stain on the ceilin...	Room 336	Painting	Critical		2026-02-26
73	Shower tap	Room 099	Plumbing Fittings	Critical		2026-02-26
102	Toilet seat	Room 093	Fixtures	Critical		2026-03-09
119	Public gents toilet (crisis wh...	General Task	Plumbing Fittings	Critical		2026-03-13
125	Toilet seat	Room 424	Plumbing Fittings	Critical		2026-03-13
131	Ice maker	General Task	Fixtures	Critical		2026-03-16
143	Balcony door key	Room 083	Fixtures	Critical		2026-03-16
151	Roller iron and 2 Dryers	General Task	Fixtures	Critical		2026-03-17
154	Basement gents toilet	General Task	Plumbing Fittings	Critical		2026-03-18
160	2 plug sockets	Room 095	Elec Power	Critical		2026-03-19
166	Entrance door	Room 426	Fixtures	Critical		2026-03-20
167	Entrance door	Room 443	Fixtures	Critical		2026-03-20
168	Entrance door	Room 446	Fixtures	Critical		2026-03-20
172	Toilet seat	Room 082	Fixtures	Critical		2026-03-20
173	Tissue holder	Room 045	Fixtures	Critical		2026-03-20
174	Toilet	Room 056	Plumbing Fittings	Critical		2026-03-21
175	Bulb	Room 052	Elec Lighting	Critical		2026-03-21
176	Ice maker	General Task	Fixtures	Critical		2026-03-22
144	1st and 2nd lounge	General Task	Fixtures	High		2026-03-17
145	Floor tiles	Room 064	Buildings	High		2026-03-17
161	Electrical Socket	Room 095	Elec General	High		2026-03-19
169	Balcony window	Room 092	Painting	High		2026-03-20

85	Installation of metal frame fo...	Reception	Buildings	Normal	2026-03-02
116	Installation of pool bar frid...	Gardens Gym	Fixtures	Normal	2026-03-12
120	Public ladies toilet (crisis w...	General Task	Plumbing Fittings	Normal	2026-03-13
122	Opposite ladies Public toilet	General Task	Painting	Normal	2026-03-13
142	Geyser leak? Kingsley	General Task	Plumbing Supply	Normal	2026-03-16
148	Balcony windows	Room 098	Painting	Normal	2026-03-17
149	Balcony windows	Room 089	Painting	Normal	2026-03-17
150	Balcony windows	Room 086	Painting	Normal	2026-03-17
156	Business centre	General Task	Elec Lighting	Normal	2026-03-18
157	Bar heater	Room 441	Elec General	Normal	2026-03-18
159	Bathroom bulb	Room 442	Elec Lighting	Normal	2026-03-19
164	Bedside bulb	Room 061	Elec Lighting	Normal	2026-03-19
170	Balcony window frames	Room 094	Painting	Normal	2026-03-20
171	Balcony window frames	Room 095	Painting	Normal	2026-03-20
177	LIGHTS NOT WORKING	General Task	Elec Lighting	Normal	2026-03-22
28	Leak Emmanuals roof	Emmanuals	Buildings	Low	2026-02-12
68	Malawi chairs painting	General Task	Painting	Low	2026-02-25
92	Disconnect Baines solar panels	General Task	Plumbing Supply	Low	2026-03-03
93	Isolate queensgate solar panel...	General Task	Plumbing Supply	Low	2026-03-03
114	Add glass to bar hanger	Wild Date	Fixtures	Low	2026-03-11

147	Ceiling bulb	General Task	Elec Lighting	Low	2026-03-17
-----	--------------	-----------------	---------------	-----	------------
